

# Oil Field Environmental Incident Summary

**Incident:** 20140307162239      **Date/Time of Notice:** 03/07/2014 16:22

**Responsible Party:** WILLISTON EXPLORATION, LLC

**Well Operator:** WILLISTON EXPLORATION, LLC

**Well Name:** DAVIS CREEK 1-32H

**Field Name:** DAVIS CREEK

**Well File #:** 15087

**Date Incident:** 3/7/2014

**Time Incident:** 09:00

**Facility ID Number:**

**County:** BILLINGS

**Twp:** 139

**Rng:** 100

**Sec:** 32

**Qtr:**

**Location Description:**

**Submitted By:** Jared Schoch

**Received By:**

**Contact Person:** Jeff White  
7500 SAN FELIPE SUITE 600  
HOUSTON, TX 77063

**General Land Use:** Cultivated

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

	Spilled	Units
Oil	6	Barrels

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None. Spill is contained in temporary dike, near no water sources and sitting on frozen ground.

**Areal Extent:**

**Potential Environmental Impacts:**

None. At current time ground is frozen and spill will be cleaned up before oil can soak into soil.

**Action Taken or Planned:**

Temporary dike built to stop spill from contaminating anymore area. Treater drained and burner gasket replaced. Crews working on cleaning up and disposing of any contaminated material, grass, dirt, etc. Future action is to change gaskets more often to avoid the possibility of another spill.

**Wastes Disposal Location:****Agencies Involved:****Updates**

---

**Date:** 3/9/2014      **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Release from a treater leak sprayed or flowed off location. Followup is necessary.

---

**Date:** 3/10/2014      **Status:** Inspection

**Author:** Miller, Adam

**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Dikes in place to prevent runoff, but more work is needed. Will call company contact tomorrow to discuss.

---

**Date:** 4/30/2014    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 17:15 4/30/14.

Small amount of oil on the lease location with no visible crude remaining off of location.

No followup is necessary.